

Schlossnagel

INVOICE

DATE	INVOICE #
1/4/10	1671

BILL TO
SKIP HANSON

SHIP TO

YEAR
MAKE <i>ARNOLT</i>
MODEL

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
LABOR	REMOVE & DISASSEMBLE FUEL CELL/PLUMBING FOR INSPECT.			
	FUEL SAFE POLYETHYLENE CELL CONDITION GOOD.			
	FLAPPER VALVE ROTTEN & CRUMBLED. FORM GOOD.			
	REPLACE FLAPPER & RE-INSTALL.	4.25		403.75
	REMOVE STEERING "RAG JOINT". CUT & PUNCH NEW MATERIAL, REPLACE HARDWARE. (ORIGINAL COUPLING CRACKED & TORN.)	40		380.00
	TOTAL LABOR			783.75
PARTS	CONVEYER BELT MATERIAL			
	MISC. HARDWARE			15.00
	FUEL CELL PLATE GASKET	1		—

In further consideration of sale and delivery it is understood and agreed that all auto racing parts sold, including running gear or engines, are subjected to abnormal stress and are not guaranteed by seller as to performance or length of service.

Total Labor	783.75
Parts	15.00
Sublet Repairs	
Shipping	
Sales Tax	1.46
Total Amount	\$ 800.21
Less Deposits	
Balance Due	