

Estimate

David Billingham

david@dbillingham.wanadoo.co.uk

19/9/ 2010

Q6768

Strip inspect and rebuild as required,
Gearbox has problems shifting gear.

3x Moog valves exchange price for 3 these should be £1200 each	2750.00
Clutch actuator internals	300.00
Latshaft, "without gear set"	800.00
Seal kit	125.00
Gear oil	120.00
Hydraulic service and rig test	1500.00
Crack test	300.00
Labour	700.00

PARTS TOTAL	5495.00
LABOUR	700.00
TOTAL	£6595.00
VAT @ %20	

TOTAL DUE	£
------------------	----------

ADVISE ,

HYDRAULIC PROBLEMS,
THE BAULK OF THESE HAVE BEEN CAUSED BY THE GEARBOX HAVING BEEN SAT DORMANT FOR A LONG TIME, THE MAIN ISSUE STEMS FROM THE CLUTCH ACTUATOR WHERE RUST/CORROSION HAS FORMED AROUND THE INTERNAL MOVING PARTS, WHEN USED AFTER BEING STATIONARY FOR A TIME THE RUST FRAGMENTS HAVE MOVED ORUND IN TO THE HYDRAULIC SYSTEM AND DAMAGE THE MOOG VALVES, THERFORE CAUSING A DIFICULT AND LAZY SHIFT.

THE ABOVE LAYSHAFT IS CRACKED AROUND THE 2ND GEAR GERNAL AND WILL MRE THAN DEFINATLRY BTREK WHEN USED AGAIN, THIS WAS PROBALY CAUSED BY LOTS OF LAUNCH CONTROL STARTS WHEN LAST RALLIED.

Payment Terms:

Payment must be made before collection of goods.

All goods remain the property of Bridge Motorsport Limited until payment is received in full.

Cheques to be made payable to :
Bridge Motorsport Limited

Company Reg No: 6752698

VAT Reg No: 971 5263 10

Wire Transfer Information
Bridge Motorsport Limited
Branch: Natwest Banbury
Sort Code: 60-01-35
Number: 52180611
IBAN: GB41NWBK60013552180611
SWIFTBIC: NWBKGB2L